




Lower Providence FD
Job #39472

THIS REPORT CONTAINS PHOTOS OF:

- The cab in the paint process.
- The body is metal finished.
- The pump house progress.
- The chassis before paint with the VIN
- The water tank has arrived.



GLICK

FIRE EQUIPMENT COMPANY, INC.















